# 2022 Maidstone Lake & Tributary Water Quality Monitoring Results: Lay Monitoring Program and LaRosa Partnership Program

Mark Mitchell, Lake Monitoring and Community Outreach Coordinator
VT Department of Environmental Conservation, UVM Lake Champlain Sea Grant










# Lay Monitoring Program (LMP) Lake Sampling Overview

- Weekly from Memorial Day to Labor Day (minimum of 8 samples for summer mean):
  - Basic Sampling: Measure Secchi disk transparency depth (clarity)
  - Supplemental Sampling: Collect water samples with hose at twice Secchi depth that are lab tested for total phosphorus (nutrient) concentration and chlorophyll-a (algae) concentration
  - Complete a lake sampling webform (and report cyanobacteria conditions)



https://dec.vermont.gov/watershed/lakes-ponds/monitor/lay-monitoring




#### Vermont Lake Score Card Maidstone Lake

https://dec.vermont.gov/watershed/lakes-ponds/data-maps/scorecard


Scores


Water Quality Data


Lake Information





Learn How Lakes Are Scored















Sampling Date	Hose Sample Depth (m)	Hose Total Phosphorus (ug/l)	Surface Total Phosphorus (ug/I)	Hose Chlorophyll-a (ug/l)	Surface Chlorophyll-a (ug/L)	Secchi Depth Without View Tube (m)	Secchi Depth With View Tube (m)
6/2/2022	18	6.9	6.9	2.14	1.01	8.9	8.9
6/10/2022	17.8	8.8	7.8	1.57	0.8	8.9	8.9
6/15/2022	20	10	8.4	1.54	0.75	9.4	10.4
6/24/2022	20	8.9	7.4	1.88	0.93	8.2	9.4
7/1/2022	20	11.7	6.8	1.52	1.08	8.7	9.7
7/7/2022	20	9	7.2	1.73	0.76	9.3	10
7/15/2022	20	7.2	5.8	1.19	0.85	10.5	11.7
7/23/2022	20	10.4	8.2	1.39	1.08	11.6	11.8
7/29/2022	20	16.3	7.9	2.09	1.22	10	
8/4/2022	20	10.7	8.4	1.26	0.75	9.1	10.1
8/11/2022	20	11.4	6.3	1.95	1	8	9.4
8/23/2022	20	9	8.5	1.67	0.95	8.5	9.6
9/7/2022	20	6.4	5.6	1.26	0.79	10.5	11.5
Mean	19.7	9.7	7.3	1.6	0.9	9.4	10.1
VT Class A1 Standards	Photosynthetic Zone	12	12	2.6	2.6	5	5

#### MAIDSTONE LAKE

#### Annual Data (Station 1)

#### Annual Data (Station 1)

9	Days Sampled	Secchi	Secchi View Tube	Chloro- a	Summer TP	Spring TP		Days Sampled	Secchi	Secchi View Tube	Chloro- a	Summer TP	Spring TF
Year		(m)	(m)	(µg/l)	(µg/l)	(µg/l)	Year		(m)	(m)	(µg/l)	(µg/l)	(µg/l)
1979	17	7.3	ķ.			6.0	2001	14	9.8		1.3	5.4	
1980	14	8.2				4.0	2002	14	7.8		2.0	5.6	
1981	13	7.7				6.0	2003	12	8.5		1.7	7.2	5.3
1982						4.0	2004	12	9.7		1.3	6.9	
1983						7.0	2005	14	9.5		1.3	6.3	6.1
1984						5.0	2006	13	8.6		1.4	7.7	7.6
1985						6.0	2007	13	8.5		1.6	6.3	6.3
1986						6.0	2008	13	8.2		1.8	9.8	6.1
1987						6.0	2009	13	8.1		1.8	6.5	7.6
1989	11	8.6		2.0			2010	14	9.6		1.3	8.2	10.0
1990	14	8.2		2.0			2011	14	8.9		1.2	7.3	7.0
1991	13	7.7		1.3			2012	14	9.6		1.2	6.9	
1992	13	8.4		1.7			2013	15	10.0		1.7	6.7	
1993	14	9.5		2.0			2014	15	9.4		1.4	8.5	
1994	13	7.5		1.8	6.2		2015	16	10.5		1.8	7.3	
1995	13	9.2		1.6	5.8		2016	14	10.8		1.2	7.3	
1996	14	8.3		1.8	4.6		2017	15	10.7		1.2	7.1	7.7
1997	14	7.9		1.5	5.4		2018	15	11.2		1.2	7.4	5.8
1998	13	7.5		1.4	4.9		2019	14	9.4		1.4	6.4	9.0
1999	14	8.7		2.1	5.5	4.3	2020	14	10.9		1.7	8.0	
2000	13	8.9		1.7	7.2		2021	13	8.8		1.8	7.7	6.3
/T Standa	aro*	2.6		7.0	18.0		VT Stand	dard*	2.6		7.0	18.0	



# LaRosa Partnership Program (LPP) Tributary Sampling Overview

- LPP first sampled in 2022 ~biweekly from April to August + storm events
- 523557-LakeMTBrookBridge
  - Major tributary to Maidstone Lake


# LPP Sample Parameters Overview

# **Total Phosphorus**


- Impacts
  - Feeds plants, algae and cyanobacteria
  - Aquatic Biota, Aesthetics, Recreation Uses
- Human Sources
  - Runoff from roads, lawns, agriculture, logging
  - Malfunctioning septic systems
- Vermont Water Quality Standards Nutrient Criteria for Aquatic Biota Use (+ Biological Criteria)
  - Not to be exceeded at low median monthly flow (baseflow) during June through October
  - 12 ug/L for small high gradient streams (SHG)
  - 15 ug/L for medium high gradient streams (MHG)
  - 27 ug/L for warm-water medium gradient streams and rivers (WWMG)


## Total Nitrogen

- Impacts
  - Feeds plants, algae and cyanobacteria
  - Aquatic Biota, Aesthetics, Recreation Uses
- Human Sources
  - Runoff from roads, lawns, agriculture, logging
  - Malfunctioning septic systems
- Vermont Water Quality Standards
  - Not to exceed 5.0 mg/l as NO3-N at flows exceeding low median monthly flows, in Class B(1) and B(2) waters.
  - Not to exceed 2.0 mg/l as NO3-N at flows exceeding low median monthly flows, in Class A(1) and A(2) waters at or below 2,500 feet elev.




#### High-Resolution Land Cover Summary




















## 2022 Maidstone Lake Tributary Monitoring Total Phosphorus Results



Mean Total Phophorus	(ug/L)	24.0
Minimum Total Phosphorus	(ug/L)	13.8
Maximum Total Phosphorus	(ug/L)	44.6




### 2022 Maidstone Lake Tributary Total Nitrogen Monitoring Results



Mean Total Nitrogen	(ug/L)	0.37
Minimum Total Nitrogen	(ug/L)	0.32
Maximum Total Nitrogen	(ug/L)	0.42

# USGS Streamflow – E. Branch of Passumpic R.



# 2022 Monitoring Summary & 2023 Next Steps



- Lay Monitoring Program (LMP)
  - 2022 Summary: Hose samples have slightly higher total phosphorus concentrations than surface samples, but both correlate with Secchi and chl-a
  - 2023 Next Steps: LMP volunteer collects biweekly surface while LMP coordinator collects water quality vertical profile during visit; add caffeine testing as human wastewater indicator (i.e. septic systems)
- LaRosa Partnership Program (LPP)
  - 2022 Summary: LakeMTBrookBridge had increasing TP, 3X higher during freshet
  - 2023 Next Steps: LPP volunteer continues collecting biweekly samples through August and investigate tributary upstream for potential problem areas